

⊕ RIVET

⊕ RIVET

⊕ RIVET

RIVET ⊕

RIVET ⊕

RIVET ⊕

⊕ RIVET

P/N E32-3122
HEEL PLATE-PASS.
MAT'L: .050 ALUMINUM
THIS SIDE FACING UP

⊕ RIVET

⊕ RIVET

⊕ RIVET

⊕ RIVET

P/N E32-3123
HEEL PLATE-PILOT
MAT'L: .050 ALUMINUM
THIS SIDE FACING UP

⊕ RIVET

⊕ RIVET

⊕ RIVET

⊕ Dzus

⊕ Dzus

⊕ Dzus

⊕ Dzus

⊕ Dzus

⊕ Dzus

P/N E32-6121
SEAT BOTTOM-ACCESS PANEL
MAT'L: .050 ALUMINUM
THIS SIDE FACING UP

LOCATE FOR BEST FIT
AVOID FASTENERS FOR
ECU MOUNTING PLATE
UNDERNEATH

BEND RADIUS AND ANGLE TO MATCH SEAT BOTTOM (PASSENGER SIDE)

WARNING

The construction and operation of Home-Built Aircraft of this type is demanding and could inflict serious injury and possible death. Each operator, distributor, manufacturer, assembler, builder, seller (and its agents, servants, employees, contractors, successors and assigns) makes no warranties, express or implied regarding the clarity or correctness of the plans, ease of construction or operation, number of building hours required, nor the safety of this aircraft or any part thereof. Furthermore, buyer (and his heirs, administrators and assigns) releases and holds seller (and its agents, servants, employees, contractors, successors, and assigns) harmless from any and all liability, damages, and causes of action, which may be incurred by buyer or any third party as a result of the purchase, use, construction and operation of this aircraft. Seller admits no liability for any injury or damage, or any loss of responsibility relative to the construction and/or operation of said aircraft. Seller admits no liability by publication of this warning.

TEMPLATE E01-1290

A600 TALON REV B SEP-07-2016

